



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:							
Company	Dennis Oakley Environmental Engineer						
OGM	Karl Houskeeper Environmental Scientist III						

Inspection Report

Permit Number:	C0150018		
Inspection Type:	COMPLETE		
Inspection Date:	Monday, November 24, 2008		
Start Date/Time:	11/24/2008 8:00:00 AM		
End Date/Time:	11/24/2008 12:30:00 PM		
Last Inspection:	Monday, October 13, 2008		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 25 Deg. F. InspectionID Report Number: 1844

Accepted by: jhelfric

12/8/2008

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: DEER CREEK MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

19,722.21	Total Permitted		
98.05	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground ☐ Surface **✓** State County ☐ Loadout Processing Fee ☐ Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspec	tor's	Signature:

Karl Houskeeper, Environmental Scientist III

Monday, November 24, 2008 Date

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Inspection Continuation Sheet

Permit Number: C0150018 Inspection Type: COMPLETE

Inspection Date: Monday, November 24, 2008

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- Post Fix the Inspections the General Sevaluated.
 Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		V	
2.	Signs and Markers	V		V	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	V			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V		~	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		V	
4.e	Hydrologic Balance: Effluent Limitations	V		~	
5.	Explosives	V			
6.	Disposal of Excess Spoil, Fills, Benches	V			
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		V	
8.	Noncoal Waste	V		V	
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	V			
11.	Contemporaneous Reclamation	V			
12.	Backfilling And Grading	V			
13.	Revegetation	V			
14.	Subsidence Control	V			
15.	Cessation of Operations	V			
16.a	Roads: Construction, Maintenance, Surfacing	V			
16.b	Roads: Drainage Controls	V			
17.	Other Transportation Facilities	V			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check	V			
20.	Air Quality Permit	V		V	
21.	Bonding and Insurance	V		V	
22	Other				

Permit Number: C0150018 Inspection Type: COMPLETE

Inspection Date: Monday, November 24, 2008

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/015/0018 was issued effective 02/07/2006 and expires 02/07/2011.

- -Certificate of Insurance policy number X0720A1A08, issued 08/28/2008 and terminates 08/28/2009.
- -UPDES permit # UT0023604 effective 12/01/2007 and expires @ midnight 11/30/2012.
- -Air Quality permit DAQE-AN0239003-02, issued June 14, 2002.
- -SPCC Plan dated 02/27/04. The Plan is P.E. certified, stamped, signed and dated by a Utah P.E.

2. Signs and Markers

The ID signs contained the necessary information. New signs have been installed with updated address information.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds were inspected on 9/21/2008.

4.d Hydrologic Balance: Water Monitoring

Second quarter 2008 water monitoring information is in the EDI website and has been uploaded. Water monitoring is current.

4.e Hydrologic Balance: Effluent Limitations

The September and October 2008 discharge monitoring reports were reviewed. No parameters were exceeded.

7. Coal Mine Waste, Refuse Piles, Impoundments

The third quarter 2008 refuse pile inspections were done on September 26, 2008 and P.E. certified on October 28, 2008.

8. Noncoal Waste

Numerous items of noncoal waste items were observed around the perimeter of the shop, especially near the noncoal waste storage area. This has been a problem in the past and enforcement action was taken at that time. The items were being picked up after surface crews were notified. Future enforcement action will be taken if the problems continues to exist or occur.

20. Air Quality Permit

Approval order AN0239003-02 was issued on 06/14/2002 and remains in effect.

Permit Number: C0150018
Inspection Type: COMPLETE

Inspection Date: Monday, November 24, 2008

Inspection Continuation Sheet

Page 4 of 4

21. Bonding and Insurance

The bond is set at \$4,118,000. It includes the new Rilda Facilities. The bond was recently raised by \$5,000 by the installation of the approved switch gear in Rilda Canyon. There are 19,722.21 permitted acres of which 98.05 are disturbed acres.